



Unit must be mounted using
nylon hardware provided.
DO NOT overtighten the
nylon screws to avoid
stripping the threads.

Heritage MedCall, Inc.
202 East Virginia Avenue
Tampa, FL 33603
813-221-1000 (voice)
813-223-1405 (fax)
www.heritagemedcall.com

Title			HM-DPS Dual Patient Station		
Size	Number			Rev	
A	HM-DPS-SCH				
Date	January 2003		Drawn by		
Filename	DPS.sch		Sheet		of